*Monroe County Surveyor's Office Corner ID: Polk_N19*

Polk_N19

# LAND CORNER RECORD

| | | | | |
|---|---|---|---|---|
| Index: T-14 | Corner: C-W1/16 | | | *State of Indiana - Hoosier National Forest* |
| Section: 27 | Township: 7N | Range: 1E | P.M.: 2nd | County: Monroe |
| Coordinate: | Lat./N: 1371749.528 | Long./E: 3146545.453 | | Datum: NAD83 IN West Zone, US Survey Feet |

## CORNER HISTORY: (Chronological history of corner)

| 1.) Date of Survey: | Surveyor: | Monument: | Recording Information: | |
|---|---|---|---|---|
| 8/22/1982 | Ken Anderson L.S. #80040545 | Monument set | USDA Forest Service Bedford, IN | |
| Reference Objects: | Species: | Diameter: | Bearing: | Distance: |
| | | | | |
| | | | | |
| | | | | |
| Record evidence of prior survey: | | | | |

| 2.) Date of Survey: | Surveyor: | Monument: | Recording Information: | |
|---|---|---|---|---|
| | | | | |
| Reference Objects: | Species: | Diameter: | Bearing: | Distance: |
| | | | | |
| | | | | |
| | | | | |
| Record evidence of prior survey: | | | | |

Monument Photograph:

## ACCESSORIES: Bearing and distance from monument to witness object.

| Reference Objects: | Object or Tree Species: | Diameter: | Bearing: | Distance: |
|---|---|---|---|---|
| | Pine* | 11" | N45°W | 56.74' |
| | Pine | 14" | S51°E | 104.21' |
| | Fire Hydrant | N/A | S60°W | 106.54' |
| * = no paint | | | | |
| Monument Found or Set: | A mag nail with a washer stamped "BRCJ INC 6892 IN" set 0.1' below grade. | | | |

## MONUMENT SKETCH




## NARRATIVE REFERENCE:

Monument is a mag nail with a washer stamped "BRCJ INC 6892 IN" set 0.1' below grade, located 4' west the white paint stripe on the shoulder of State Road 446, 20' west of the centerline, 40' north of Forestry Trail #4721.070, 200' south of a drive to Kilmer residence.

## SECTION DIAGRAM




Corner Location = ●

## PERPETUATION RECORD:

The monument was set and maintained by establishing two new bearing trees and one new reference object.

Two new bearing trees were marked with a blaze, scribed B.T., bearing tree sign and mag nail.

*Referenced on BRCJ survey recorded as InstNo.2018007752*

*Accepted by the Monroe County Surveyor Review Board on August 6, 2019.*

| | | |
|---|---|---|
| Section: 27 T7N R1E | Prepared By: BRCJ (Project#3-0822) | Date: 5/2018 |

Monroe County Surveyor's Office Corner ID: Polk_N19

Index No. T-14 (Alphabetical – Numerical)

# LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-5680-11 (5/12/61)

T. 7 N R. 1 E 2nd Mer. N.F. Hoosier County Monroe State Indiana

CW1/16 Corner common to sections 22 , , and

## EXISTING SURVEYS

### Original Government Survey

Year surveyed

Original monument (Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species

Diameter

Bearing

Distance

### Original Evidence Found

Year of search By

Monument found

Original Bearing Trees Found

Species

Diameter

Bearing

Distance

### Subsequent Corner Restoration

Year surveyed By

Where filed or recorded

Monument (Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species

Diameter

Bearing

Distance

### Evidence of Subsequent Corner Restoration Found

Year of search By

See Corner Card S.O



Sketch

○ Corner ▨ F.S. Land

### Relation of Evidence to Record Features Along Section Lines

Section line to sections

Object

Record distance

Measured distance

### Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

### Perpetuation Record

Monument and accessories established. Include brief description of area.

At time of search:

1. Did you have the record description? Yes No

2. How was search area located? Pacing, chaining, photos, maps, etc.

3. Man hours spent in search

4. Do you think additional search might recover evidence? Yes No

5. Signature

Certified corner restoration certificate prepared: Yes No

Filed in county records at Date County Document No.

Identified on aerial photo No. Which is filed at